PATENT

I hereby certify that on the date specified below, this correspondence is being deposited with the United States Postal Service as first-class mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

_____Jan. 23, 2008_____   _____Beverly Loken_____

Date   Beverly Loken

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants : Daniel B. Penney and Steven So   Attorney Docket No.: 500794.01

Patent No. : US 7,003,643 B1

Issued   : February 21, 2006

Title   : BURST COUNTER CONTROLLER AND METHOD IN A MEMORY DEVICE OPERABLE IN A 2-BIT PREFETCH MODE

NOTIFICATION OF ERRORS

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

The following errors were noted in a review of the above-identified letters patent. One or more of these errors was inadvertently made in the original application, while the others occurred in the printing of the patent. Since the errors are of an obvious nature, a formal Certificate of Correction is not believed to be warranted at this time. Therefore, applicants request that this notification be placed in the Patent and Trademark Office file.

Column, Line	Reads	Should Read
Column 2, Line 67	"generated by an incrementing a burst"	--generated by incrementing a burst--
Column 6, Line 32	"it can be see"	--it can be seen--
Column 8, Line 55	"the coumter""	--the counter--

Column 10, Line 41	"at least one data storage devices"	--at least one data storage device--
Column 10, Line 6	"a dynamic random access memory, comprising"	--a dynamic random access memory, comprising:--
Column 11, Line 39	"at least one data storage devices"	--at least one data storage device--
Column 11, Line 42	"a dynamic random access memory, comprising"	--a dynamic random access memory, comprising:--

Respectfully submitted,

Date: _Jan. 22, 2008_   By: _Edward W. Bulchis_

Edward W. Bulchis, Reg. No. 26,847
Customer No. 27,076
Dorsey & Whitney LLP
1420 Fifth Avenue, Suite 3400
Seattle, WA 98101
(206) 903-8785
Attorneys of Record

EWB:tdp

Enclosure:
    Postcard

500794.01 notification of errors